

Brother MFC-L2750DW — Unit Condition Summary

Serial Number: U64988E9N679171 **Manufactured:** May 2018 **Total Page Count:** 18,403 pages

Usage Summary

This printer has accumulated approximately **18,400 lifetime pages**.

Using Brother's approximately **50,000-page device-life reference** for this platform as a comparison, the recorded page count represents approximately **37% of that reference**.

In other words, the printer remains at approximately **63% below the referenced 50,000-page level**.

The historical average print coverage is approximately **4%**, consistent with ordinary office document and text printing.

Approximately **29% of the printer's historical output was duplex**, indicating regular but normal use of the automatic two-sided printing system.

Usage History

The internal counters indicate predominantly normal business/office use.

Recorded lifetime statistics include:

- Approximately **18,400 total pages**

- Approximately **5,344 duplex pages**
- Approximately **13,059 standard-output pages**
- **4 recorded paper jams** over the printer's lifetime
- No recorded duplex jams

The very small number of recorded paper jams relative to the total page count indicates that the paper-feed mechanism has historically operated reliably.

Consumable History

The printer's internal history records:

- **7 toner cartridge replacements**
- Previous Replace Drum warnings near the end of its prior operating period

The printer was acquired with the drum counter indicating that the previous drum had reached the end of its calculated service life.

The previous consumables have been removed.

New Drum and Toner

The printer has now been serviced with:

- **New compatible DR-730 drum unit**
- **New compatible high-yield toner cartridge**

These are aftermarket/compatible consumables rather than genuine Brother components.

The drum replacement procedure was completed and the printer now reports:

- **Drum Life: approximately 100%**

- **Toner Life: approximately 100%**
- **Drum Replacement Count: 1**

Print quality after installation of the new drum and toner is ****clean and good****.

Current Condition

The printer has been cleaned and functionally tested.

Printing is currently clean and consistent with the newly installed drum and toner.

Printing, automatic duplex operation, scanning, and document-feeder operation have been tested.

The exterior shows normal cosmetic signs of previous business use. Major plastic components, covers, trays, and functional parts are intact.

Overall Assessment

Moderate previous business use / good current functional condition.

The printer has accumulated approximately **37% of Brother's referenced 50,000-page device-life figure** for this platform.

Its internal history is consistent with normal office use rather than unusually heavy printing:

- Approximately 18,400 lifetime pages
- Historical average coverage of approximately 4%
- Only 4 recorded paper jams
- No recorded duplex jams
- New compatible drum installed
- New compatible high-yield toner installed

- Drum and toner currently reporting approximately 100% life
- Clean current print quality

The printer was manufactured in **May 2018** and is currently operating normally.

A post-service Printer Settings report was printed after installation and reset of the new drum and confirms the current consumable status and lifetime page count.